

This drawing, specifications, and concepts contained here in are the sole property of Red Barn Machine, and may not be reproduced or used in any fashion without the prior written permission of Red Barn Machine.

	REVISIONS										
REV	DESCRIPTION	DATE	INITIAL	APPROVED							
Α	CH'D REF. DIM FROM 5.75 TO 4.5, ADDED REF. DIM. 2.4 & 18' PER R.W.	11/28/11	RJC	RW							
1	ADDED TOLERANCE ±.06 TO .50, 5.3, 2.4 & .75 DIMS, CH'D OVERALL LENGTH FROM 5.2 & LENGTH BETWEEN CENTER OF WRENCH AND SOCKET FROM 4.5, CH'D TOOL NAME FROM WRENCH PER D.W.	3/14/12	RJC	DW							





 \triangle BELOW INFORMATION FOR OUTSIDE OPERATION

- 1. FORM WRENCH
- 2. WELD SOCKET TO REF. LENGTH
- 3. CUT EXCESS WRENCH & FINISH END

NOTE:

- 1. REMOVE WELD MARKS WITH WIRE WHEEL.
- 2. TOOL ALSO SOLD W/KIT RBT18561.

ASS QT	Y ASSY Y QTY	B/O	PART#	UNIT QTY	DESCRIPTION	MATERIAL	B/O INFORMATION OR SPECIFICATIONS
	\times		-1	1	WELDMENT		
	1		-3		WRENCH		3/8" 12pt. BOX END PROTO #212ASD (MSC #84504158)
	1		-5		SOCKET		3/8" DR. 9MM PROTO #5209M (MSC #70548573)
	ASSY #						

® RED BARN MACHINE TITLE TORQUE ADAPTER T/R G/B DWG NO. REV RBT18582 UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ON: DECIMALS DRAWN BY: CLDUGH APPROVED D Weil .XXX ± .005 .XX ± .01 .X ± .1 FRACTIONS ± 1/32 SEE NOTE ANGLES ±.5° USED ON MODEL UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING SCALE NTS DATE 7-17-09 SHEET of 1

Entered:Date:				CAPT			
	WORK ORDER NON-CONF	WORK ORDER NON-CONFORMANCE / ROUTE UPDATE					
NCR No.			Route update only				
Job:	DISPOSITION	DEPARTMENT/PROCESS					
Part No. RBT18582	Rework X Scrap Use-as-is	Skid-tube Cross tub Machining x Small Fa Large Fab Finishin	b Prod. Eng. Coor	. Water Jet			
Date: 22.09.19	Sequence #:	QTY Affected :		MRB (QSI042) SAD			
Description ¹	Work Order Deviation	Disposit	22.09.13				
Drawing doesn't state to ren details on purchase part (Soc	nove company markings/Engraving cket)	Acceptable remove up to ma material on socket to remove supplier,	Completed By				
				QC / QA Coordinator			
Root Cause		FAULT CATEGOR	Y				
Operator Manufacturing Process Equip/Tooling Handling/Presservation Material Product Improvement × Process Improvement Human Factors	Pressure/Forced Bending Crushing Cracks Crimp/Kink/Ripple/Wave/Twist Marks/Chatter Mislabeled Other/Details:	Contamination Misaligned/off center BOM/Route Broken/Damage/Defect Incomplete/Unclear Instructions Drill Holes Fit/Function	Power Loss/Surge Folio/Program Grain Direction Weld Wrong Stock Pulled Out of Sequence Off-set/Set-up	Positioned Wrong Outside Tolerance X Drawing Finish Part Lost/Missing Misread			
	f			l			